

Daily Completion Report

Well ID: 55-29 Field: Newberry

AltaRock Energy Inc.

Well Name: Newberry 55-29

Report No: 28	Report For 06:00 AM October 21, 2012		
Project Manager: Michael Moore	Cost Incurred to Date:	\$4,461,983.63	State: OR
Measured Depth (ft.): 10,060	Field Tickets:		County: Deschutes
Vertical Depth (ft.):			Field: Newberry
Plug Back MD:			
Plug Back TVD:			

Current Operations: Continue running stim pump 1 and continue to ramp up on pump speed while controlling inlet injection pressure and flow rate.

Prior Operations: Install RFR sump pump and continue to ramp up on pump speed while controlling inlet injection pressure and flow rate.

Planned Operations: Continue to run stim pump 1 and try to increase WHP until hydro shearing observed. Go into stage 1 of stimulation.

Well site Supervisors: Ted DeRocher Michael Moore Tel No.: 775-830-7406 541-410-1795 Operations Summary for Oct. 20th From То Elapsed Code Operations Description 7:08 7.13 134.000 INJ Stim pump speeds increased slowly to 1369 psi WHP; WHP fluctuationg (+/- 85 psi). 0:00 Held pumps steady until WHP equilibrated. Increased pump speeds thereafter until both pumps 134.000 INJ 7:08 9:57 2.82 tripped at 9:37; pumps back up at 9:57 and ramping up (37.8/36.9 Hz). Stimp pumps tripped due to low suction pressure. Both pumps back online at 11:13 and ramping up INJ 9:57 134.000 11:05 1.13 (35.7/35.1 Hz). WHP at 781. dp: 664 gpm. Ultrasonic: 47 gpm. 11:05 14:09 3.07 134.000 INJ Stim pump 2 tripped. Both back online at 14:22 and ramping up pump 1 only (36.3/35-constant) 14:09 15:41 1.53 134.000 INJ Ramp up pump 2 slowly. Stim pump 2 tripped and ramped up repeatedly. Max. WHP: 1751 psi with dP 600 gpm and INJ 15:41 0:00 8.32 134.000 ultrasonic 86 gpm. Issued PO's VENDOR AMOUNT DESCRIPTION

Activity Comments
Stim pump 2 having significant tripping issues. No seismic events related to stimulation recorded.