

Daily Completion Report

Well ID: 55-29 Field: Newberry

Alta Rock Energy Inc.

Well Name: Newberry 55-29

Project Manager: Michael Moore		Cost Incurred to Date:	\$4,482,478.92	State: OR	
Measured Depth (ft.): 10,060 Field Tickets:		Field Tickets:		County: Deschutes	
Vertical Depth (ft.):				Field: Newberry	
Plug Back MD:					
Plug Back TVD:					

Current Operations: Pump repair. Running stim pump 2.

Prior Operations: Pump repair. Running stim pump 2.

Planned Operations: Continue running Stim Pump 2. Inject diverter and tracers when stim pump 1 repaired (likley one week out).

Well site Supervisors: Ted DeRocher Michael Moore Tel No.: 775-830-7406 541-410-1795

Operations Summary for Nov. 10th									
From	То	Elapsed	Code		Operations Description				
0:00	11:00	11.00	134.000	INJ	Starting at 0:53 there was an unexplained pressure drop fro gpm flow rate drop) over a 10 minute period. Because a sin Pump #1 on 11/07 at 04:00 prior to the pump suffering far w later, we ramped stim pump 2 down to 45Hz, resulting in a w down hole ~170 gpm. Re-fueled generators at shift change	nilar drop occurred on Stim orse problems 4 hours			
11:00	0:00	11.00	134.000	INJ	Running stim pump 2 at 45 Hz overnight. Bypass valve 47% open. Globe valve 9-1/4 turns throttled.WHP: 720. Injection down hole: 170 gpm.				
Issued PO's									
VENDOR		AMOUNT		DESCRIPTION					

Activity Comments

Trouble shooting on stim pump 1 determined that shaft no longer drives some impellers, they keys locking them must be sheared. Pump #1 decoupled from the line and prepared to send back to Oklahoma for repairs. Status of repairs to spare pump, already in OK, is being checked. Pump 1 to be repaired next week. Injection of tracer and diverter is on hold until 2 pumps are running.

Max. well head pressure reached today: 1275 psi (prior to 0:53) Max. flow through pumps before bypass: 758 gpm (prior to 0:53)

Max. flow down hole: 255 gpm

Volume pumped down hole today: 249,778 gallons

Total injected volume: 5,001,032 gallons. A memo with further explanation for upward change of injected volume is being prepared.

Seismic Activity: Five seismic events located by Foulger consulting over 24 hour period (four shown on LBL site, none on PNSN site). This is the most events since 11/02 when the WHOP was much higher. Further description of these events will be in a seismicity report later today.

Entered: 11/11/2012

Page: 1 of 1